



OVERHEAD SHOWER	
Size	18x18
Holes	100
HYDROMASSAGE	
Jets	4
Holes	24
HANDSHOWER	
Holes	38

Working water pressure 2-6 bar | Ideal water pressure 3-4 bar